





Service Letter No. 459

October 6, 1965

TO:

Distributors, Dealers, Certified Service Centers and Owners

SUBJECT:Mixture Control Cable ShieldMODELS AFFECTED:PA-24-400, Serial Nos. 26-1 to 26-124 inclusiveCOMPLIANCE DATE:At the next 50 hour inspection

Several reports have been received of binding or broken mixture control cables on the PA-24-400. This binding or breaking has generally occurred in the engine compartment at the fuel injection servo end of the control.

A shield has been added in the engine compartment to protect the mixture control. (See sketch on the reverse side of this letter.)

This shield should be ordered under part number 25079-00. When this shield is installed discard clamp presently used.

Credit will be allowed for the shield and one (1) hour of warranty labor on receipt of a Warranty and Credit Claim.

<u>NOTE</u>

The mixture control should be inspected for condition and proper operation before installation of shield 25079-00.

PIPER AIRCRAFT CORPORATION. LOCK HAVEN, PA., U. S. A.

