



SERVICE BULLETIN

No.187

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

FAA APPROVED

April 15, 1960

TO: All Distributors, Dealers, Owners and Piper Certified Service Centers

SUBJECT: PA-24 and PA-24-250 Landing Gear Safety Switches - Service Letter
#314A, dated June 8, 1959

This Bulletin is to advise that the installation of Service Kits No. 754 217 and No. 754 221 has been made mandatory.

Service Letter No. 314A, dated June 8, 1959, outlines the procedure to be followed for compliance with this Bulletin and the serial numbers affected.

The date of compliance shall be prior to but not later than August 1, 1960.

It is requested that a report be mailed to the Service Department indicating the date of compliance. This report must also include those airplanes that have been modified previously and which comply as a result of Service Letter 314A.
