



# SERVICE *No.* BULLETIN

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

NUMBER 171

March 18, 1959

SUBJECT: Weight and Balance

MODELS AFFECTED: PA-24 and PA-24 "250"

The arms aft of datum for the Omni Antenna, Whip Antenna and the Narco LFR-3 installation in the weight and balance section of the Airplane Flight Manual are incorrect for airplanes with serial numbers 24-1 to 24-790 inclusive. The arms shall be changed to conform with the following information.

	<u>Arms Aft Datum</u>
Omni Antenna (Serials 24-1 to 24-790 inclusive)	(268.0)
Whip Antenna (Serials 24-1 to 24-88 inclusive)	(99.0)
Whip Antenna (Serials 24-89 to 24-790 inclusive)	(159.0)
Narco LFR-3 Installation (Serials 24-103 to 24-790 inclusive)	(135.0)

The V12-P5 power supply should be crossed out on all Flight Manuals because the weight and arm is included in the Narco LFR-3 installation.

After the above corrections have been made, attach this bulletin to the Weight and Balance as the authority for this change.

End.