

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

FAA DOA EA-1 Approved

December 7, 1966

Subject: Fuel Purge Valve Hose Replacement

Models Affected: PA-24-400 Comanches

Serial Numbers Affected: 26-1 to 26-148 incl. Applicable only to aircraft that have had Fuel System Purge Valve Kit 756 922 installed.

Compliance Date: Fuel Purge Valve Hose Assembly, part number 25551-04, (reference Service Bulletin No. 228) must be disconnected immediately, if not previously accomplished, at fuel injector fitting and fitting must be capped with AN929-4 cap. The subject hose must remain disconnected until the requirements of this bulletin have been completed.

Reason For Bulletin: Deterioration of Fuel Purge Valve Hose Assembly, part number 25551-04 necessitates replacement

Material Required: Fuel Purge Valve Hose Replacement Kit 757 099

Installation Instructions: Contained in Kit 757 099

Availability of Parts: Piper Dealer

Warranty Parts Allowed: Fuel Purge Valve Hose Replacement Kit 757 099

Warranty Labor Allowed: Two (2) Hours

Expiration Date of Warranty: March 30, 1967

----- PIPER DISTRIBUTORS ONLY -----

Disposition of Replaced Parts: Destroy. Not necessary to return parts

NOTE: Fuel Purge Valve Hoses, part number 25551-04, that are in distributor or dealer stock and those contained in Fuel Purge Valve Installation Kit 756 922 or Fuel Purge Valve Hose Assembly Kit 756 994 must be replaced with Kit 757 099. Credit will be issued for hoses 25551-04 that are stocked as indicated above upon receipt of a Warranty & Credit Claim.