



# SERVICE LETTER

No. 569

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

December 28, 1970

---

Subject: Engine Compartment Modifications

Models Affected: PA-24-260 Comanche "C"

Serial Numbers Affected: 24-4783, 24-4804 to 24-4903 incl., 24-4905 to 24-4913 incl., 24-4915 to 24-4934 incl.

Compliance Time: Recommended at the next 100 hour or annual inspection, whichever occurs first.

Purpose: To provide material and instructions to modify the power-plant on the above referenced aircraft, as follows:

1. Installation of an air take-off assembly and a fuel pump cooling baffle which will increase the cooling air flow to the fuel pump;
2. Replacement of the existing alternate air induction hose with an improved hose assembly and instructions for adding a drain hole.

Instructions: Contained in Engine Compartment Modification Kit No. 760 463.

Material Required: One (1) each (per aircraft) Engine Compartment Modification Kit No. 760 463.

Availability of Parts: Your Piper Dealer.

Summary: Material for this modification will be provided to you free of charge through your Piper Dealer providing the Compliance Time period is adhered to.

---